



- Factory - R&E
Zilog
conf.

November 27, 1990

2601 11th Avenue N. Extension
Nampa, Idaho 83687

Telephone (208) 466-4551
FAX (208) 467-9765

CERTIFIED MAIL # P 574 665 995

CR-FVI

Brian R. Monson, Manager
Hazardous Materials Bureau
Division of Environmental Quality
Idaho Dept. of Health and Welfare
1410 N. Hilton
Boise, ID 83706

Dear Mr. Monson:

Thank you for your letter regarding the soil sample results of Zilog's waste solvent tank removal project. Samples ZLG-01 and ZLG-03 were taken from under the ends of the tank. Sample ZLG-02 which indicated 26ppm of acetone was taken from under the middle of the tank.

Although your letter indicated no remedial action was required, Zilog removed the soil which was between the waste solvent tank and its concrete anchoring slab. The volume of this soil was approximately equal to one fifty-five gallon drum. The soil was shipped on November 7, 1990 to USPCI for disposal on hazardous waste manifest VWR05.

Copies of Zilog's Permit for Removal or Abandonment of UST's and Zilog's UST's Permanent Closure Form are attached for your consideration.

If you have any questions or comments concerning the attached documentation, please don't hesitate to contact me. Thank you for your assistance in this matter. I look forward to working with you again in the future.

Sincerely,


Richard G. Price III, IHIT
EPA/OSHA Engineer

attachments

cc: file.

USEPA SF



1643309